

## The M7.3 Vancouver Island Earthquake of 1946



*Courtenay B.C., chimney collapse through roof of elementary school*



*Courtenay B.C., damage to interior of elementary school*



*Courtenay B.C., damage to the Canadian Imperial Bank of Commerce*



*Courtenay B.C., masonry failure of post office*



*Comox B.C., earthquake damage and house foundation failure*



*Comox B.C., earthquake damage on Comox Road*